




Sposób montażu / Installation method / Спосіб монтажу

- 2. Montaż bezpośredni
- 2. Surface mounting
- 2. Накладний монтаж



5 LVM 48V, 150W,
INSIDE POWER SUPPLY
aluminum


10161



6 LVM OUTSIDE POWER SUPPLY
CONDUCTIVE MODULE

plastic


10168



7 LVM STRAIGHT
CONDUCTIVE MODULE

plastic


10167



8 LVM CORNER
CONDUCTIVE MODULE

plastic

10166




9 LVM INSIDE CORNER

aluminum

10165

includes 2xLVM TRACK BUCKLE CONNECTOR




10 LVM HORIZONTAL
CORNER

aluminum

10164

includes 2xLVM TRACK BUCKLE CONNECTOR



11 LVM TRACK BUCKLE
CONNECTOR

steel

10171